

Material Safety Data Sheet

page 1

Identity UB5322001 T2131/T2141/T2151/TX4511/TX5511 TX1511/TX2511/TX6511/TX6311					
SECTION I					
Manufacturer's Name Fuji Kagakushi Kogyo Company Limited	Emergency Telephone Number (06) 471-7071				
Address 8-43, Utajima 4-chome, Nishi Yodogawa-ku, Osaka 555, Japan	Telephone Number for Information (06) 471-7071				
	Date Prepared Dec. 16, 1991				
SECTION II - Hazardous Ingredients/Identity Information					
Hazardous Components	CAS No.	OSHA PEL	ACGIH TLV	Other Limits	
Paraffin Wax (fume) Carbon Black	8002-74-2 1333-86-4	N/A 3.5mg/m ³	2.0mg/m ³ 3.5mg/m ³	N/A N/A	
Predominant Components Coloring material Wax Resin Additive Polyethyleneterephthalate film		Not Applicable			
SECTION III - Physical/Chemical Characteristics					
Melting point	N/A	Specific Gravity	N/A		
Boiling Point, Evaporation Rate	N/A	Vapor Pressure/Density	N/A		
Solubility in Water No data					
Appearance and Odor Polyethyleneterephthalate film coated on one side there of with black ink.					

FUJI KAGAKUSHI KOGYO COMPANY LIMITED

UB5322001

SECTION IV - Fire and Explosion Hazard Data				
Flash Point	N/A		Flammable Limits	LEL N/A UEL N/A
Extinguishing Media	Water mist, Foam, Dry powder, CO ₂ gas, others			
Special Fire Fighting Procedures	N/A			
Unusual Fire and Explosion Hazards	None			
SECTION V - Reactivity Data				
Stability	Unstable		Condition to Avoid N/A	
	Stable	X		
Incompatibility (Material to Avoid)			None	
Hazardous Decomposition or Byproducts			None	
Hazardous Polymerization	May Occur		Condition to Avoid N/A	
	Will Not Occur	X		
SECTION VI - Health Hazard Data				
Route(s) of Entry: Inhalation? Skin? Ingestion?				
No Yes Yes				
Health Hazards (Acute and Chronic) No data available				
Carcinogenicity: NTP? IARC Monographs? OSHA Regulated?				
No No No				
Ames Test : Negative				
Signs and Symptoms of Exposure No data available				
Medical Conditions Generally Aggravated by Exposure No data available				
Emergency and First Aid Procedures Wash away with soap and water an ink sticking to skin. If ink has contacted eye, wash it with enough water, then consult a doctor.				

SECTION VII - Precautions for Safe Handling and Use				
Steps to Be Taken in Case Material is Released or Spilled				
An inadvertently released or rewound ribbon should be wound again on the reel.				
Waste Disposal Method				
Dispose in accordance with local, state and federal regulations.				
Precautions to Be Taken in Handling and Storing				
Should be stored at dark and cold place.				
Other Precautions				
None				
SECTION VIII - Control Measures				
Respiratory Protection (Specify Type)				
None				
Ventilation	Local Exhaust	N/A	Special	N/A
	Mechanical (General)	N/A	Other	N/A
Protective Gloves		Eye Protection		
N/A		N/A		
Other Protective Clothing or Equipment				
N/A				
Work/Hygienic Practices				
None				